

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/18/2018 10/18/2018	Sterling York

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_4				
Comment Code					
Inspector Comment					
LD 9 has flood fight supplies on hand and coordinates with other local levee districts in the flood fight supply staging program.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_5				
Comment Code					
Inspector Comment					
The levee district has stated in the past that they have a copy of the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_6				
Comment Code					
Inspector Comment					
The district has attended the Flood Fight class put on by RD 784 and DWR.					

No Photos

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/18/2018 10/18/2018	Sterling York

LM Start	0.03	Rating **	A	Issue No.	1
LM End	6.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.169237 °	39.255682 °
				-121.622989 °	-121.636386 °
DWR ID	DWR_LD0009_01_f _ 2018_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Fall 2018.					

View looking upstream landside at the well maintained annual vegetation, Fall 2018.

LM Start	0.03	Rating **	A	Issue No.	2
LM End	6.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.169237 °	39.255682 °
				-121.622989 °	-121.636386 °
DWR ID	DWR_LD0009_01_f _ 2018_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Fall 2018.					

View looking upstream waterside at the well maintained annual vegetation, Fall 2018.

LM Start	0.09	Rating **	M	Issue No.	18
LM End	0.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.170064 °	39.170064 °
				-121.622563 °	-121.622563 °
DWR ID	DWR_LD0009_01_f_ 2016_18				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
No rodent activity was observed, holes need to be backfilled. Fall 2018					

A photograph showing a patch of green grass growing in a dry, sandy area. In the background, there is a dirt path and a white structure, possibly a building or a fence. A date stamp '09/26/2017' is visible in the bottom right corner.

View on landside of rodent activity and holes.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/18/2018 10/18/2018	Sterling York

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---